




ARTIC SEALS



Material	Speed m/s:	temperature ??C:	pressure Mpa:
Pu	1	-30 +90	2,5

Code	Description	d	D	Thickness	GROOVE DEPTH	Material	Weight
01.CSA00.006010	CSA D.006x010x3,4/3,7	6.00	10.00	3.40	3.70	Pu	10.00
01.CSA00.0080116	CSA D.008x011,6x3/3,3	8.00	11.60	3.00	3.30	Pu	0.05
01.CSA00.009515	CSA 009 D.009,5x015x4/4,5	9.50	15.00	4.00	4.50	Pu	0.38
01.CSA00.010018	CSA D.010,0x018x6,5/7	10.00	18.00	6.50	7.00	Pu	0.89
01.CSA00.012018	CSA D.012,0x018x4,3/4,8	12.00	18.00	4.30	4.80	Pu	10.00
01.CSA00.012020	CSA 012 D.012,0x020x6,5/7	12.00	20.00	6.50	7.00	Pu	1.00
01.CSA00.014022	CSA 014 D.014,0x022x6,5/7	14.00	22.00	6.50	7.00	Pu	1.22
01.CSA00.016024	CSA D.016,0x024x6,5/7	16.00	24.00	6.50	7.00	Pu	10.00
01.CSA00.018026	CSA D.018,0x026x6,5/7	18.00	26.00	6.50	7.00	Pu	1.30
01.CSA00.020028	CSA 020 D.020,0x028x6,5/7	20.00	28.00	6.50	7.00	Pu	1.56
01.CSA00.022030	CSA D.022,0x030x6,5/7	22.00	30.00	6.50	7.00	Pu	1.70
01.CSA00.025033	CSA 025 D.025,0x033x6,5/7	25.00	33.00	6.50	7.00	Pu	1.87
01.CSA00.028036	CSA D.028,0x036x6,5/7	28.00	36.00	6.50	7.00	Pu	2.04
01.CSA00.030040	CSA D.030,0x040x6,5/7	30.00	40.00	6.50	7.00	Pu	2.90
01.CSA00.032042	CSA 032 D.032,0x042x6,5/7	32.00	42.00	6.50	7.00	Pu	3.07
01.CSA00.036046	CSA D.036,0x046x6,5/7	36.00	46.00	6.50	7.00	Pu	3.44
01.CSA00.040050	CSA 040 D.040,0x050x6,5/7	40.00	50.00	6.50	7.00	Pu	3.45
01.CSA00.050060	CSA D.050,0x060x6,5/7	50.00	60.00	6.50	7.00	Pu	4.77
01.CSA00.057074	CSA 057 D.057x074x12/12,5	57.00	74.00	12.00	12.50	Pu	13.60
01.CSA00.070087	CSA 070 D.070x087x12/12,5	70.00	87.00	12.00	12.50	Pu	17.40
01.CSA00.078095	CSA 078 D.078x095x12/12,5	78.00	95.00	12.00	12.50	Pu	18.45