




Parker Pradita



Materiale	Velocita' m/s:	Temperatura ??C:	Pressione Mpa:
Pu	0,5	-35 +100	40

Codice	Descrizione	d	D	Spessore	H Sede	Materiale	Peso
01.BS000.040050	BS 4005 P5008 D.040x050x10/11	40.00	50.00	10.00	11.00	Pu	10.00
01.BS000.004553	BS 4553 P5008 D.045x053x5,6/6,3	45.00	53.00	5.60	6.30	Pu	0.00
01.BS000.070085	BS 7085 P5008 D.070x085x11,4/12,5	70.00	85.00	11.40	12.50	Pu	10.00
01.BS000.090105	BS 9005 P5008 D.090x105x11,4/12,5	90.00	105.00	11.40	12.50	Pu	0.00
01.BS000.110130	BS B030 P5008 D.110x130x14,5/16	110.00	130.00	14.50	16.00	Pu	56.45
01.BS000.200225	BS L025 P5008 D.200x225x18,2/20	200.00	225.00	18.20	20.00	Pu	10.00